


Report No. : EED32O81897701


Page 34 of 42

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: DBP-82A5B



Radiated spurious emission Test Setup-1(Below 1GHz)










Report No. : EED32O81897701







Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

