


Project No.: 24032709-03

Set-Up for Conducted Emission Test





Lab: <u>Hwa-Hsing (Dongguan) Testing Co., Ltd.</u> Address: <u>No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial</u> <u>Park, HuangJiang Town, Dongguan City, People's Republic</u> <u>of China</u>

Tel: 0769-83078199 Web.: www.hwa-hsing.com E-Mail: customerservice.dg@hwa-hsing.com

Release Ver. 1.5



Project No.: 24032709-03

Set-Up for Radiated Emission Test




Lab: <u>Hwa-Hsing (Dongguan) Testing Co., Ltd.</u> Address: <u>No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial</u> <u>Park, HuangJiang Town, Dongguan City, People's Republic</u> <u>of China</u>

Tel: <u>0769-83078199</u> Web.: <u>www.hwa-hsing.com</u> E-Mail: <u>customerservice.dg@hwa-hsing.com</u>

Release Ver. 1.5



Project No.: 24032709-03



-End-

Lab: <u>Hwa-Hsing (Dongguan) Testing Co., Ltd.</u> Address: <u>No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial</u> <u>Park, HuangJiang Town, Dongguan City, People's Republic</u> <u>of China</u>

Tel: <u>0769-83078199</u> Web.: <u>www.hwa-hsing.com</u> E-Mail: <u>customerservice.dg@hwa-hsing.com</u>

Release Ver. 1.5