


Report No.: EED32N80617801


Page 48 of 58

8 PHOTOGRAPHS OF TEST SETUP

Test Model No.: MW-JS1



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32N80617801





Conducted Emissions Test Setup



There are absorbing materials under the ground









