

Appendix A: Test Configuration Test Photographs

Photograph 5: AC Conducted Emissions – Front View - TC #1



Photograph 6: AC Conducted Emissions - Rear View – TC #1



Photograph 7: AC Conducted Emissions – Front View - TC #2



Photograph 8: AC Conducted Emissions - Rear View – TC #2



Photograph 9: AC Conducted Emissions – Front View - TC #3



Photograph 10: AC Conducted Emissions - Rear View – TC #3



Photograph 11: Radiated Emissions – TC #1; Concrete Container



Photograph 12: Radiated Emissions – TC #1; Steel Container



Rhein Tech Laboratories
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: VEGA Grieshaber KG
Model: VEGAPULS 69
ID's: O6QPS60XW1/3892A-PS60XW1
Standards: FCC 15.209/IC RSS-211
Report Number: 2016249-209

Photograph 13: Radiated Emissions – TC #1; Fiberglass Container



Photograph 14: Radiated Emissions – TC #2; Concrete Container



Photograph 15: Radiated Emissions – TC #2; Steel Container



Photograph 16: Radiated Emissions – TC #2; Fiberglass Container



Photograph 17: Radiated Emissions – TC #3; Concrete Container



Photograph 18: Radiated Emissions – TC #3; Steel Container



Photograph 19: Radiated Emissions – TC #3; Fiberglass Container

