

Report No.: EED32Q80244001

Page 59 of 76

7 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)(left ear)



Radiated spurious emission Test Setup-2(Above 1GHz)(left ear)















Report No.: EED32Q80244001





Radiated spurious emission Test Setup-3(Below 1GHz)(right ear)



Radiated spurious emission Test Setup-4(Above 1GHz)(right ear)













Report No.: EED32Q80244001

