Project No: JB-Z0418 Page 43 of 45

6. Photographs of test setup

The following photographs show the arrangement of the worst case.


6.1. AC Power-line Conducted Emissions Measurement Photo(s)






6.2. Antenna-port Conducted Measurements Photo(s)

Maximum Peak Conducted Output Power





Others





Project No: JB-Z0418 Page 44 of 45


6.3. Radiated Spurious Emissions Measurement Photo(s)














Project No: JB-Z0418 Page 45 of 45

<EUT Axis>







The antenna was tested with attached to supporting jig that does not affect EMC characteristic in order to place for each axis.

<EUT Zoom>

