

ATTACHMENT TO SETUP PHOTOGRAPHS

This document contains 1 photograph of unintentional RE test
Reference: test report TELRAD_FCC.15716_rev1

Photograph No.1
Unintentional radiated emissions measurement setup in the anechoic chamber with double ridged guide antenna

