





## **8 PHOTOGRAPHS OF TEST SETUP**



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Page 34 of 52 Report No.: EED32Q81209201



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.

