

Report No.: EED32L00319901 Page 50 of 61

PHOTOGRAPHS OF TEST SETUP

Test model No.: Tapio I



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)





Report No. : EED32L00319901 Page 51 of 61



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There are absorbing materials under the ground.
























Conducted Emissions Test Setup





















































