

## **Photographs**

## 7.1 Radiated Emission Test Setup

**Below 1G** 



Above 1G



Dongguan Yaxu (AiT) Technology Limited No.22, Jinqianling Third Street, Jitigang, Huangjiang,Dongguan, Guangdong, China



Report No.: E-F1701001 Page 73 of 80 Rev: 00

## 7.2 Conducted Emissions Test Setup

