

Prüfbericht - Nr.: 16004610 001
Test Report No.:

Seite 13 von 16
Page 13 of 16

6 Photographs of the Test Set-Up


Photograph 1: Set-up for Continuous Disturbance Voltage on AC Mains



Prüfbericht - Nr.: 16004610 001
Test Report No.:

Seite 14 von 16
Page 14 of 16

Photograph 2: Set-up for Radiation Measurement Below 30MHz



Prüfbericht - Nr.: 16004610 001
Test Report No.:

Seite 15 von 16
Page 15 of 16

Photograph 3: Set-up for Radiation Measurement below 1GHz

