

Report No.: T140320L08-RP1


FCC ID: CJ6UPSUM3KBBT


Date of Issue: April 8, 2014

8 PHOTOGRAPHS OF TEST SETUP

Radiated Emission Setup Photos

Below 1GHz







Report No.: T140320L08-RP1

FCC ID: CJ6UPSUM3KBBT

Date of Issue: April 8, 2014

Above 1GHz






Compliance Certification Services Inc.

Report No.: T140320L08-RP1 FCC ID: CJ6UPSUM3KBBT

Conducted Emission Setup Photo



Date of Issue: April 8, 2014



Compliance Certification Services Inc.

Report No.: T140320L08-RP1 FCC ID: CJ6UPSUM3KBBT Date of Issue: April 8, 2014

Power Line Conducted Emissions Setup Photos



