




PHOTOGRAPHS OF TEST SETUP

Test model No.: GWP-SLCR2-BT-V2



Radiated spurious emission Test Setup-1 left ears(Below 1GHz)



Radiated spurious emission Test Setup-2 left ears(Above 1GHz)















Report No.: EED32N81130401 Page 39 of 55



Radiated spurious emission Test Setup-1 right ears(Below 1GHz)



Radiated spurious emission Test Setup-2 right ears(Above 1GHz)














Report No.: EED32N81130401 Page 40 of 55



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions









