


Report No. : EED32L00320701 Page 200 of 207

PHOTOGRAPHS OF TEST SETUP

Test model No.: W5LM2001





Radiated spurious emission Test Setup-1/2(Below 30MHz)









Report No.: EED32L00320701







Radiated spurious emission Test Setup-3/4Below 1GHz)





















Report No. : EED32L00320701 Page 202 of 207



Radiated spurious emission Test Setup-5(Above 1GHz)



Radiated spurious emission Test Setup-6(Above 1GHz)
There are absorbing materials under the ground.



















Report No.: EED32L00320701

Page 203 of 207







































































