




B66(20.0M) 64QAM 1@0 132072 CH




B66(20.0M) 64QAM 100@0 132072 CH




B66(20.0M) 64QAM 1@99 132572 CH




B66(20.0M) 64QAM 100@0 132572 CH




B66(15.0M) 64QAM 1@0 132047 CH




B66(15.0M) 64QAM 75@0 132047 CH




B66(15.0M) 64QAM 1@74 132597 CH




B66(15.0M) 64QAM 75@0 132597 CH




B66(10.0M) 64QAM 1@0 132022 CH




B66(10.0M) 64QAM 50@0 132022 CH




B66(10.0M) 64QAM 1@49 132622 CH




B66(10.0M) 64QAM 50@0 132622 CH




B66(5.0M) 64QAM 1@0 131997 CH




B66(5.0M) 64QAM 25@0 131997 CH




B66(5.0M) 64QAM 1@24 132647 CH




B66(5.0M) 64QAM 25@0 132647 CH




B66(3.0M) 64QAM 1@0 131987 CH



B66(3.0M) 64QAM 15@0 131987 CH




B66(3.0M) 64QAM 1@14 132657 CH




B66(3.0M) 64QAM 15@0 132657 CH




B66(1.4M) 64QAM 1@0 131979 CH




B66(1.4M) 64QAM 6@0 131979 CH



B66(1.4M) 64QAM 1@5 132665 CH



B66(1.4M) 64QAM 6@0 132665 CH



APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

*** End of Report ***

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.
